


CP-358774-1 35076-183-1 - NORRIS


Figure 1

CP-358774-1 35076-183-1 - NORRIS



CP-358774-1 35076-183-1 - File: P746.raw - Type: 2Th/Th locked - Start: 3.000 ° - End: 40.040 ° - Step: 0.040 ° - Step time: 1.0 s - Temp.: 27.0 °C - Time Started: 16 s - 2-Theta: 3.000 ° - Theta: Operations: Import

CP-358774-1 35076-183-1 - NORRIS




CP-358774-1 35076-183-1 - File: P7748.raw - Type: 2Th/Th locked - Start: 3.000 ° - End: 40.040 ° - Step: 0.040 ° - Step time: 1.0 s - Temp.: 27.0 °C - Time Started: 16 s - 2-Theta: 3.000 ° - Theta: 1.500 ° -
Operations: Import

CP-358774-1 35076-076-1 - NORRIS

Figure 3


CP-358774-1 35076-076-1 - NORRIS



CP-358774-1 35076-076-1 - File: L992.raw - Type: 2Th/Th locked - Start: 3.000 ° - End: 40.000 ° - Step: 0.040 ° - Time Started: 16 s - 2-Theta: 3.000 ° - Theta: 1.500 ° - Phi: Operations: Import

Figure 4

CP-358774-1 35076-076-1 - NORRIS



CP-358774-1 35076-076-1 - File: L992.raw - Type: 2Th/Th locked - Start: 3.000 ° - End: 40.000 ° - Step: 0.040 ° - Step time: 1.0 s - Temp.: 27.0 °C - Time Started: 16 s - 2-Theta: 3.000 ° - Theta: 1.500 ° -
Operations: Import